



P54.18-3260-09

Short designation	Designation	Cable colors	Cable colors	Notes
G3/3x1	Left O2 sensor upstream TWC [KAT] connector	RDGN — 1 BNBK — 2 GN — 3 BK — 4	— — — —	
G3/5x1	Left O2 sensor downstream TWC [KAT] connector	BNGY — 1 RDGN — 2 BNWH — 3 BU — 4	— — — —	
X18/33 (4)	SPS [PML] connector	GNVT — 1 GNPK — 2	— GNVT — GNPK	
X26	Interior and engine wiring harness connector	BNGY — 1 RDGN — 2 BNWH — 3 BU — 4 BNBK — 5 RDGN — 6 BNWH — 7 YE — 8	— BNGY — RDGN — BNWH — BU — BNBK — RDGN — BNWH — YE	
X26 (1)	Interior and engine wiring harness connector	BUGN — 1 — 2 VTWH — 3 RDGN — 4	— BUGN — RDBU — VTWH — RDGN	M271 M271 M271 M271
X26/27	Front PTS separation point	BKYE — 1 BNBU — 2 BKWH — 3 WHRD — 4 YEWB — 5 YEVN — 6 YERD — 7 BUYE — 8	— BKYE — BNBU — BKWH — WHRD — YEWB — YEVN — YERD — BUYE	PTS PTS PTS PTS PTS PTS PTS PTS

X62 (1)	RPM sensor connector (signal)	BK — 1) BK BKGN — 2) BKGN WH — 3) WH WHGN — 4) WHGN BKPK — 5) BKPK BKRD — 6) BKRD	
X62/7	Left front axle electrical distributor connector, major assembly compartment	— 1) BKYE	
		— 2) YE	