

MODEL 211.0 /2

with CODE (489) Airmatic (semi-active air suspension)

with CODE (600) Headlamp cleaning system



P82.15-2088-07

Shown on left telescopic nozzle

1 Telescopic nozzle

2 Telescopic nozzle flap

3 Bolt

4 Securing clamp

5 Tubing

	Remove/Install		
1.1	Remove left front headlamp unit	When removing left telescopic nozzle (1).	AR82.10-P-4730TA
2.1	Fold open telescopic nozzle flap (2)	When removing right telescopic nozzle (1).	
3.1	Unscrew bolt (3).	When removing right telescopic nozzle (1).	
4.1	Remove bottom engine compartment paneling at front	Model 211.042/043/056/061/065/070/ 076/080/082/083/242/243/256/261/ 265/270/276/280/282/283 Model 211.042/043/061/065/070/076/ 080/082/083/242/243/261/265/270/ 276/280/282/283	AR61.20-P-1105T
4.2	Remove bottom part of noise encapsulation at the front.	Model 211.004/006/016/023/026/028/ 206/216/223/226	AR94.30-P-5300T
5.1	Place telescopic nozzle (1) to rear of engine compartment until the locking clip (4) is accessible	When removing right telescopic nozzle (1).	
6	Press retaining clip (4) and detach hose (5) from the telescopic nozzle (1)		
7	Remove telescopic nozzle (1)		
8	Install in the reverse order		
9	Check headlamp cleaning system for proper function		
	Windshield wipers, windshield washer system and headlamp cleaning system - function check		AP82.30-P-8252A